

Item no 5.8

QUESTION NO 8

By Councillor Osler for answer by the Convener of the Transport and Environment Committee at a meeting of the Council on 3 May 2018

Several roads including Craigmook Road which were surface dressed last year are due to be redone as the original work was so poor that it did not even survive the first frost.

Question (1) How many different sets of road repairs from last year, across the city have already been or are due to redone during 2018-19?

Answer (1)

Question (2) Breakdown by Ward?

Answer (2)

Question (3) What investigation has been done to find out why the surface dressing did not work?

Answer (3)

Question (4) What measures have already been put in place to prevent the same issues from reoccurring and are any further measures in plan?

Answer (4)